




Unimog U1100 Refurbishment


Vehicle Inspection




Exterior Inspection



Interior Inspection




Cab Removal



Cargo Tray Disassembly



Disassembly & Part Inspection



Disassembly & Part Inspection



Overhaul Preparation



Engine Overhaul




Transmission Inspection




Transmission Overhaul



Wheel Hub Repair



Axle Disassembly



Drive Shaft & Axle Repair [Before – After]



Before



After


Suspension Part Replacement



Injection Pump Repair & Fuel Line Replacement



Part Replacement



Brake Grinding [Before – After]



Before



After

Brake Liner Replacement [Before – After]



Before



After

Wooden Bench Repair [Before – After]



Before



After

Cab Repair [Before]



Cab Repair [After]



Canvas Replacement [Before – After]



Before

After


Vehicle Painting



Vehicle Painting



Vehicle Painting



Cab Restoration [Before – After]



Before

After

Electrical Repair [Before – After]



Before

After

Dashboard Repair [Before – After]




Before



After

Tire Replacement [Before - After]



Before

After

Vehicle Delivery



Vehicle Delivery



Vehicle Delivery



Vehicle Delivery

